

MX Series Voice Gateway Release Notes

Version: Rev 1.9.82.344.P5 Date: June 17, 2016

Firmware Modules

Model \ Component	Software Version	Kernel Version
HX4E	Rev 1.9.82.344.P5	Kernel 2.0.10.p1
MX8A	Rev 1.9.82.344.P5	Kernel 2.0.10mt.p1
MX60	Rev 1.9.82.344.P5	Kernel 3.0.9

New Features

None

Improvements

None

Bugs Fixed

1. Fixes a bug that caused HX4E/MX8A to obtain a new IP address after replugging the WAN cable.
2. Resolves an issue that caused a poor voice quality for MX60 G.729 recording.
3. Resolves a bug with message waiting indication in FSK mode. .
4. Resolves a bug that caused the HX4E/MX8A fail to reboot after binary upgrading.
5. Resolves an issue with batch configuration of SIP trunks on the MX60.