MX100G SIP-ISDN Gateway Release Notes

Version: Rev 2.1.5.91.P8   Date: Jan. 22, 2016

Firmware Modules

Modules	Version
Software version	Rev 2.1.5.91.P8
Hardware version	Rev 2.0.0
Kernel version	Kernel 2.0.14
DSP version	Rev 1.8.199

New Functions

None

Improvements

1. Supports taking caller information from PAI header of INVITE message and presenting it in the Calling Party Number information element in the ISDN SETUP message.
2. Add **Firmware version** on **Info** page.

Bugs Fixed

1. Fixed bug that caused the ISDN timeslot not being released when the far end fails to respond.
2. Fixed bug that caused memory leaks when the response to the OPTION message is not received.
3. No longer carries the Sending Complete information element when the SETUP message carries a partial called party number.
4. Fixed the issue in which the device did not send SIP registration message automatically upon network re-connected.
5. Fixed bug that caused the failure to cancel the registration to the SIP server under certain conditions.
6. Fixed bug that caused the display of routing table be modified automatically at the beginning of each month.