

OM20/50 IPPBX Software Release Notes

Version: Rev 2.1.5.103 Date: July 12, 2016

Firmware Modules

Model Component	OM20	OM50
Software Version	Rev 2.1.5.103	Rev 2.1.5.103
OS Version	Kernel 2.0.14	Kernel 2.0.14mt

New Functions

1. Supports using IMG file to upgrade the Kernel through auto provisioning or Web GUI.

Functions Improved

1. The Web GUI configuration of the password and PIN of trunks and extensions is no longer visible to operators.
2. Cuts short of PSTN failover time.
3. Performs periodic DNS lookup if the lookup for the API application server fails.
4. For multiple SIP registrar application, outbound calls will abort if DNS lookup of SIP server fails.

Problems Fixed

1. Fixes a bug that caused the device to obtain a new IP address after plugging and unplugging the WAN cable.
2. Fixes an issue with restoring the configurations on **Multi-site** and **Extensions>Group** to factory default.